

Spring Break Update

The contractor really did some work over Spring Break. The first picture shows the west entrance to the new gym and commons area. You can see where the contractor demolished and cut off about 20 feet of the cafeteria to make way for the new entrance. There is now a temporary wall on the north side of the cafeteria separating the cafeteria from the construction. The second picture shows the entrance to the High School. You can see steel in place for the math classroom wing, principal's offices, new entrance, and library.

